



Assembly process



1. Additionally tape the top of the sealing sleeve all around with the butyl tape section supplied.
2. Then secure this with the help of the cable tie.
3. Ready!

Subject to technical changes
and printing errors.
Version 07/2021 V1